



## SAFETY RECOMMENDATION No: 54/2013

### **Text of Safety Recommendation:**

Consider of installing a mooring buoy at the head of the inner dock for facilitating the berthing of cruise ships with length exceeding the docks length.

### **No of Safety Investigation Report:**

08/2013: Parting of a mooring line resulting in fatal injury of a seaman on cruise ship "NORWEGIAN JADE"  
(See the full Report [here.](#))

### **Safety Recommendation addressed to:**

Port facility of Katakolo

### **Date of publication:**

29/05/2015

### **Comments-Remarks:**

---