



SAFETY RECOMMENDATION No: 37/2013

Text of Safety Recommendation:

Take appropriate actions to ensure that STCW A-IV/2 and SOLAS Chapter V/Reg.14.3 & 4 requirements are fully satisfied by recruited watch keeping personnel.

No of Safety Investigation Report:	06/2013: Collision between M/V "CONSOUTH" and M/V "PIRIREIS" (See the full Report here.)
Safety Recommendation addressed to:	Owners/Managers of M/V "PIRIREIS"
Date of publication:	12/03/2015
Comments-Remarks:	---