

## **SAFETY RECOMMENDATIONS (SR) ACCORDING TO SUBJECT:**

Element 1:	Sinking – total loss
Element 2:	Ship's equipment

No	SR No	SUBJECT (Brief description)	Safety Investigation Report No
1	14/2013	Audiovisual alarm system for the increase of engine space bilge water level	03/2013
2	<u>15/2013</u>	Storing the floating device and the life buoy in a proper way to ensure that they float freely in case of barge's foundering	03/2013
3	<u>18/2013</u>	Operation of the towline release mechanism on tugs used in ports - Regulation	04/2013
4	<u>19/2013</u>	Operation of the towline release mechanism on tugs used in ports - Regulation	04/2013
5	22/2013	Watertight and weathertight openings during operation and operation of the towline release mechanism on tugs used in ports	<u>04/2013</u>
6	23/2013	Operation of the towline release mechanism on Tugs used in Ports	<u>04/2013</u>

The present document derives from a report published on the site of the Hellenic Bureau for Marine Casualties Investigation (HBMCI, <a href="www.hbmci.gov.gr">www.hbmci.gov.gr</a>) and comprises safety recommendations which were reached after safety investigations of marine casualties, according to the provisions of National Law 4033/2011, with purpose to improve maritime safety and protection of sea environment.