



## SAFETY RECOMMENDATION No: 30/2013

### **Text of Safety Recommendation:**

Take appropriate and necessary measures in order to ensure that bridge navigational team adhere Master's Standing Orders at all times.

<b>No of Safety Investigation Report:</b>	06/2013: Collision between M/V "CONSOUTH" and M/V "PIRIREIS" (See the full Report <a href="#">here.</a> )
<b>Safety Recommendation addressed to:</b>	Owners/Managers of M/V "CONSOUTH"
<b>Date of publication:</b>	12/03/2015
<b>Comments-Remarks:</b>	---