



SAFETY RECOMMENDATION No: 33/2013

Text of Safety Recommendation:

Ensure that safeguards are in place for the implementation of “Shipboard and working arrangements”.

No of Safety Investigation Report:	06/2013: Collision between M/V “CONSOUTH” and M/V “PIRIREIS” (See the full Report here.)
Safety Recommendation addressed to:	Owners/Managers of M/V “CONSOUTH”
Date of publication:	12/03/2015
Comments-Remarks:	---