



SAFETY RECOMMENDATION No: 39/2013

Text of Safety Recommendation:

Supplement fleet's SMS so as to ensure that equipment interfacing to VDR/S-VDR systems, are properly and correctly transferring data following maintenance, repair or replacement.

No of Safety Investigation Report:	06/2013: Collision between M/V "CONSOUTH" and M/V "PIRIREIS" (See the full Report here.)
Safety Recommendation addressed to:	Owners/Managers of M/V "PIRIREIS"
Date of publication:	12/03/2015
Comments-Remarks:	---