



**SAFETY RECOMMENDATIONS (SR) ACCORDING TO SUBJECT:**

<b><u>Element 1:</u></b>	<b>Fire - explosion</b>
<b><u>Element 2:</u></b>	<b>Ship's equipment</b>

No	SR No	SUBJECT (Brief description)	Safety Investigation Report No
1	<a href="#">02/2012</a>	Closed - circuit television monitoring of garages of Ro -Pax ships	<a href="#">01/2012</a>
2	<a href="#">03/2012</a>	DRENCHER fire zones	<a href="#">01/2012</a>
3	<a href="#">04/2012</a>	Maintenance and periodical inspection of DRENCHER systems	<a href="#">01/2012</a>
4	<a href="#">06/2012</a>	Patrol system (fire patrols) in garage spaces	<a href="#">01/2012</a>
5	<a href="#">08/2012</a>	Activation and operation of DRENCHER fire zones	<a href="#">01/2012</a>
6	<a href="#">09/2012</a>	Densification of closed- circuit television monitoring in closed garage spaces of the Ro-Pax ships	<a href="#">01/2012</a>
7	<a href="#">10/2012</a>	eliminating clogging phenomenon of DRENCHER heads and pipes	<a href="#">01/2012</a>

No	SR No	SUBJECT (Brief description)	Safety Investigation Report No
8	<a href="#">11/2012</a>	Periodical inspection of the equipment of electrical installation for the operation of reefer trucks / vehicles	<a href="#">01/2012</a>
9	<a href="#">12/2012</a>	Megger Test	<a href="#">01/2012</a>
10	<a href="#">13/2012</a>	DRENCHER fire zones	<a href="#">01/2012</a>
11	<a href="#">14/2012</a>	Equipment of electrical installation for the operation of reefer trucks / vehicles	<a href="#">01/2012</a>