



## SAFETY RECOMMENDATION No: 47/2013

### **Text of Safety Recommendation:**

Review the applied mooring equipment inspection system for winches band brake mechanisms by focusing on the configuration of value settings corresponding to MBL of servicing mooring lines.

### **No of Safety Investigation Report:**

08/2013: Parting of a mooring line resulting in fatal injury of a seaman on cruise ship "NORWEGIAN JADE"  
(See the full Report [here.](#))

### **Safety Recommendation addressed to:**

Owners/Managers of cruise ship "NORWEGIAN JADE"

### **Date of publication:**

29/05/2015

### **Comments-Remarks:**

---